#### DECONTAMINATION FIRE GEAR What? Why? How?

T. VERMINCK





openbare diensten services publics


SC

#### DEFINITION FIREFIGHTER **RELEVANT CONTAMINATION**

#### CHEMICAL CONTAMINATION :


- VOC's SVOC's
- PAH's
- DIOXINS
- CYANIDES
- ...
- BIOLOGICAL CONTAMINATION
  - BACTERIA
  - VIRUSES
  - FUNGI
- OTHER SPECIFIC CONTAMINATION
  - ASBESTOS
  - HEAVY METALS






2012 Encyclopædia Britannica, Inc.

#### PROTECTIVE CLOTHING EXPOSED TO PARTICLES




#### CONTAMINATED CLOTHING



#### TOXICOLOGICAL SPECTRUM FIRE GEAR

#### AFTER AVERAGE 1 INDOOR FIRE






OUTER SHELL MEMBRANE LINING




# DECONTAMINATION – WHY?



- DIRECTIVE 2004/37/EC

   CMD carcinogens or mutagens at work – art. 10
- REACH REGULATION ANNEX VII
- OEKO-TEX STANDARD
- EU PPE REGULATION 2016/425



#### INTER UNIVERSITY RESEARCH BELGIUM

A possible explanation of the results is that a large proportion of the increase in concentration is from percutaneous absorption. **Probably the fireman are continuously exposed to PAHs through continuous exhalations of its contaminated clothing (PPE).** 

# DECONTAMINATION – HOW?

Finnish Institute of Occupational Health



WELL-BEING THROUGH WORK

# Contamination and decontamination of firefighting garments –Laboratory tests

Laitinen J, Tuomi T, Vainiotalo S, Laaja T, Rantio T, Parshintsev E, Kiviranta H, Koponen J, Pyrstöjärvi P

<u>juha.laitinenen@ttl.fi</u>,

#### CONCLUSIONS

- Cleaning with water and detergents is only able to decontaminate:
  - MAX. 40% with 2 garments in the machine
  - MAX. 15% with 3 garments in the machine
- Toxic compounds transfer from more contaminated garments to the less contaminated garments during standard cleaning : CROSS CONTAMINATION
- The clothing shows severe degradation after frequent cleaning with standard processes
- Environment !


STANDARD CLEANING TECHNOLOGIES BASED ON WATER AND DETERGENTS CAN NOT BE USED FOR THE DECONTAMINATION OF FIRE INTERVENTION GEAR






#### DECONTAMINATION :

The reduction of all toxic products present in the clothing up to the legal maximum allowed quantities for this type of clothing. This without degrading the clothing and in an environmentally responsible manner.











Centexbel

#### TOXICOLOGICAL SPECTRUM FIRE GEAR

#### AFTER 80min. STANDARD H<sub>2</sub>O CLEANING







OUTER SHELL MEMBRANE LINING



#### TOXICOLOGICAL SPECTRUM FIRE GEAR

#### AFTER 27min LCO<sub>2</sub> EXTRACTION





OUTER SHELL MEMBRANE LINING





# DECONTEX TECHNOLOGY



E Electrolux

-----

-

#### DECONTEX-SMALL EXTRACTOR




#### DECONTEX MEDIUM EXTRACTOR




#### DECONTEX LARGE EXTRACTOR


### LCO<sub>2</sub> -EXTRACTION TECHNOLOGY




## DECO<sub>2</sub>FIRE<sup>®</sup> TECHNOLOGY




#### PROTECTIVE CLOTHING EXPOSED TO PARTICLES




#### CONTAMINATED CLOTHING




### AFTER H<sub>2</sub>O CLEANING



#### **CO<sub>2</sub> DECONTAMINATION**



#### AFTER CO<sub>2</sub> DECONTAMINATION



### **BIOLOGICAL CONTAMINATION**

#### From most resistant to most susceptible :


- Prions (Creutzfeldt-Jacob)
- Bacterial spores
- Mycobacterium tuberculosis
- Nonlipid viruses (polio, coxsackie)
- Fungi (aspergillus, candida)
- Vegetative bacteria (S. aureus, P aeruginosa)
- Lipid viruses (HIV, herpes, hepatitis B)



torganisme : Enterococcus faecium			Serienummer : 160068
:	Electrolux LCO2		
:	03		
:	05-12-2016		
UITGANG	ISWAARDE [kve/cm <sup>2</sup>	10 <sup>5</sup>	10 <sup>6</sup>
	$\checkmark$	2	
DR:	10 6		
	: : UITGANG	Electrolux LCO2     03     05-12-2016 UITGANGSWAARDE [kve/om <sup>2</sup> 10	Electrolux LCO2     03     05-12-2016 UITGANGSWAARDE [kve/cm <sup>3</sup> ]     10 <sup>4</sup> 10 <sup>5</sup>



STERICOO/DECONTEX – 18/09/2017 Pseudomonas aeruginosa PAO1 Staphylococus aureus Mu50




Data zijn het aantal overgebleven bacteriën na behandeling (log schaal)

# DECONTEX LCO<sub>2</sub> technology kills bacteria, viruses and fungi between factor 10<sup>6</sup> and 10<sup>7</sup>

#### **KU LEUVEN**

# SPECIFIC CONTAMINATION



#### **ASBESTOS DERIVATES**

- Serpentine
  - Chrysotile
- Amfibole
  - Amosite
  - Crocidolite
  - Tremonite
  - Actinolite
  - Anthofylite



#### HEAVY METALS (>5,0 g/cm<sup>3</sup>)

- Lead
- Cadmium
- Zinc
- ...








# SPECIFIC DECONTAMINATION

DECONTEX TECHNOLOGY CERTIFICATION 20/12/2017 – KIWA COMPLIANCE



#### **DECONTEX CLEANROOM FOR FIREFIGHTER PPE**






# DECCNTEX CLEAN TEXTILE SOLUTIONS



#### EXAMPLE VISIBILITY REPORT





WWW.DECONTEX.COM

### REÏMPREGNATION



EN 469

#### FINAL CONCLUSION DECONTAMINATION

Fire suits that are in regular use must be subjected to maintenance (incl. complete decontamination) at least <u>twice a year</u>, for reasons of :

- emptying the filter for toxic compounds and thus avoid breaktrough to the skin
- the killing of all micro-organisms, both for hygienic and health reasons
- applying the water/chemical-repellent after-treatment as prescribed in European Standard EN 469
- control of the general functionality (visibility, protection, rescue system, ...)

note: suits that have been exposed to very serious contamination must be decontaminated immediately

#### **PROJECT : PERSONAL DECON**

1 STRONG DECONTAMINATION WIPE

FOR THE FACE, NECK AND HANDS

# DECONWIPES 🧈

ON-SCENE DECONTAMINATION



CLEANSES AND REMOVES HARMFUL TOXINS FROM THE SKIN

www.mydeconwipes.com

#### **INSTRUCTION MANUAL**





Wipe whole face. Pay attention to eyelids and nostrils. Avoid direct contact with eyes.

Wipe inside and outside the ears.

Wipe the head and hair. Use multiple wipes if heavily

Wipe arms and hands.



### NEXT PROJECT FIREFIGHTER BIOMONITORING

# THANK YOU!!!!!

QUESTIONS ? tve@decontex.com